

*Design Build Masters LLC
34 Karlton Circle
Andover, MA 01810*

HEILEMANN RESIDENCE: 86 WALTHAM STREET, BOSTON, MA 02118

Replace (5) FIVE WINDOWS AS DESCRIBED INCLUDING:
MARVIN ULTIMATE (NEW) REPLACEMENT INSERT WINDOW
MINOR EXTERIOR REPAIRS TO MATCH EXISTING

ALL WORK TO BE COMPLETED FROM INSIDE THE 4TH FLOOR UNIT AS SHOWN IN THE ATTACHED
(EXTERIOR) (3) THREE PHOTOS (STREET VIEW)

- a. Two over two, aluminum clad exterior, primed wood interior
(Alternate: one over one for (4) four narrow windows with glass width less than 15.5"
- b. Completely new interior trim: stools, casings, stops, header & aprons

Respectfully:

Design Review for window muntin layout.

Options for four (4) windows under 15.5" in width

**Design Review Hearing
Presentation
APP # 24.0274 SE 86 WALTHAM
STREET**

- : a. One over One double-hung
- b. Two over Two double-hung

