(Back of) 90 Warren Ave Garden Fence Renovation Proposal

Replace missing finials with studentmade sculptures

Repair of existing broken gate

Installation of additional gate

General repaint

Replacing Missing Finials with Student Art




- 28 total missing fineals/sculptures
- Student Creative Constraint: Sculptures
 must take inspiration from an existing
 fineal design somewhere in South End,
 allowing sculptures to be unique but
 aesthetically consistent with others in
 South End
- Iron sculptures, made first in clay & cast by contractor; welded to the fence by contractor

Repairs and public art component have been cleared with BPS, MK South End Academy administration, Boston Public Art Commission, and the Browne Fund (original builders of the fence)







Sculpture creative constraints:

Must be 5-6 inches tall, 3 inches across, and min. 1.5-2 inches in thickness

Must take direct inspiration from one existing iron sculpture or finial in South End, present or past (youth can also draw reference from the 1972 South End Streets Survey photographs).

General Repairs







- Overall sanding & black re-paint (2, 3, 5, 6)
- Repair of closing mechanism on broken existing gate (4)
- Addition of wrought iron gate to currently uncovered area (1)





