


14 Mount Hood Rd

AACD Presentation

Existing Conditions:



Existing Conditions:



Scope of Work:

Replace existing non-original vinyl windows with wood windows Marvin Ultimate Wood Windows or equivalent.

- A
 - New 9-over-1 front-install muntins on upper and single pane on lower
- B
 - New transom window with 2 by 4 front-install muntins
- C
 - New double hung wood window 9 over 1 front install muntins on upper and single pane on lower
- D
 - New double hung wood window with 2 over 3 on upper and single pane on lower.
- E
 - New wood window single pane on left single pane on right.

