


# Roof Refurbishment Project – 26 Wellington Street





# Project Location



# Ask: Remove De-commisioned Chimney



- **Remove derelict chimney, which is structurally unsound, and logistically difficult to restore**

## **Rationale**

- Chimney has no historical significance
- Why: There was another building next to ours prior ( 32 Wellington) which was demolished after a fire in the late 1970's
- Chimney was not visible to public view prior to late 1970's



# Side View of Building from end of Wellington

This side of Building was only exposed in the late 70's after a fire resulted in the demolition of the adjacent structure (32 Wellington)

